Lloyds Register; Rpt of Pass. Ship Safety Survey re: Nieuw Amsterdam 5/28/00

Uloyd's Register

REPORT OF PASSENGER SHIP SAFETY SURVEY

UNDER THE PROVISIONS OF THE INTERNATIONAL CONVENTION FOR THE SAFETY OF LIFE AT SEA, 1974, AS AMENDED

N.	AME OF SHIP SIGNAL LETTERS					NATIONALITY AND PORT OF REGISTRY							GROSS TONNAGE D.			AGE	ATE KE	EL LAID																	
	1	Vi	eu	W		Τ		P	C	3 (3 (2					_	R	LA	Ī	NDS	;						3	39	30			10	4/11	/1981
4	4m	st	er	lan	a ·									1	ROTTERDAM												• •								
LF	/IM	0	NUI	MBE	₹		PC	ORT				OR1			FIRST VISIT LAST VISIT NO. VISIT																				
8	0	2	4	0	1	4	V	q	F	_		0 0	_	1 5	5 5 1 8 0 5 0 0 2 8 0 5 0								ग	히	1	8									
			L	Ц							Ţ	\perp	_		<u> </u>	_		Ĺ				_			L	L	\perp	\perp	_		<u> </u>				
FE	ES			П				T	PE	NS	Ť	T	Γ	Τ	Γ	T	01/	Ï	FEE	3	AND	E	OP E	NS	ES		7	T	1	CH	ECKL	DATES ARE T	AY, MO	NTH AN	
ш			L	Щ			1			<u> </u>	_	Щ.		ــــــــــــــــــــــــــــــــــــــ	<u> </u>	<u> </u>	<u>_</u>	L		_	ш	_				1_				(EX	CEPT	FOR PYROT	ECHNIC	<u></u>	
1.	, i		-	To	E	VEI	RA.	Live:			7.00	17.4	4.0	6.0	N.	X	4	Š.		29	(Z. 64)						× 30	Ŕ,	***	4) K.	* 4				
1.1				T ₁ /	GENERAL 1/We have carried out a Passenger Ship Safety survey on the above named ship. The survey carried out was:																														
1.2					A complete renewal survey in accordance with Chapter I, Regulation 7 of the above Convention covering																														
• •				1											-				_		Ship S		•	qui	pene	nt.									
1.3				1	•												ımin	ied	. as	lis	ted ov	erk	eaf												Ľ
1.4				^	gen	eral	exar	nina	tio	n of	vali	idity (of C	ertifi	cate																				
1.4	.1			E	ten	sion	of v	al idi(y c	of Co	ertif	icate	(see	note	6)																				
1.4	.2			Additional survey (see note 2)																															
											_							_											<u> </u>						
2.				10	EF	CTL	FIC	'A'I	I	ЙC	A	ND	D	RY	DQ	CK	AD.	Q	***					**	// /	***	***	**	*** **	V.85	37 874		X. (3)	Control of the Contro	
2.1				1				auge		•							_		_							_			_						_
2.1						e foo		ate is te)	su	ea .		N	5Î				last	ue	Date	!		L	25.	05.	99	J			Þф	try D	ate		0	1.06.00	J
				P	sse	nger	Ship	p Saf e	ety	Cer	tific	cates			•																				
				N	ow:	issue	d by	7				N	5 1				issi	ue i	Date				23.	05.	00]		1	Expi	hy D	ate		0	1.09.00]
2.2	:			c	ertif	ying	Rep	ort is	ssu	ed																		•	Yes	×	1	i		N	k 🖸
2.3				V	alidi	ity of	exi:	sting	œ	rtific	ate	exter	nde	d unt	l (sec	not	e 6)															·]
2.4				D	ry C	ocki	ng d	late/	ln	wat	er s	urvey	,																				Ŀ]
2.5				U	nde	r wa	ter e	xami	ina	tion	(se	e not	27)																				1	8.05.00]
2.6				The undersigned has verified the equipment and arrangements in the Record of Approved Passenger Ship Safety Equipment and found them to be in agreement therewith or equivalent thereto. All parts surveyed were found to be well maintained in an efficient and good working condition. (See note 5)																															
Pe	senge	r Si	hip S	afety (Certi	ficate	ma	y incl	ud	e the	Ad	dendi	in f	or the	carri	age o	f d ar	ıge	TOUS	goo	ods. (S	OL	AŚ	74/8	88 R	II -	2/54	+ 1	R VI	1/5)					
						L																_								•					
Su	rvey	or	ŚSi		ite A	AU	٩		Γ	1	Van	ne of	Sh	ip					Da 9	te ()	,	,			LR	/[МО	Νι	ımb	er	-	Report	Numbe	er .	Page
N.J. HASTINGS / A. MADDEN NIEUW AMSTERDAM 80024014 VCR 000154 1 FORM 2112 R (05/95) LLOYD'S REGISTER OF SHIPPING								1																											
	-44 2		- 21 61	~, ,,	,	~		LUE	,,,		. 3	STATE !	HA	•																					

15 V 10 IN 12 A	VALENIERANE RABBOROS	en la compa			
	DETAILED INFORMATION CONCERNING THE FO AND ATTACH ADDITIONAL SHEETS)	LLOWING IS LISTED	BELOW (IF NECESSARY USE		
	Repairs and / or renewals carried out				
				•	×
•	Alterations affecting the Passenger Ship Safety Certificat	e			
•	Renewals and/or replacements affecting the Record of Pa	ssenger Ship Safety Equi	pment and Form 2114		•
-	onboard has been amended accordingly.				
•	The relevant amended pages of Form 2114 are attached	will be forwarded to He	ad Office		
•	Any fire which has occurred on board since the last surv	еу			x
	(Item A* - General, page 1 of Survey Check List refers) The following general repairs have now been aff	ected:			
	• DEFECTS TO BE CORRECT				,
¥	 Under Water Examination reveal blade tips approx 120mm from the loss of a piece of one of the there Recommend underwater repair of thruster for the first 300mm alor show some sign of light cracking. Top deck plating located inside thickness measurement. Smoke detectors in paint locker intrinsically safe. Bridge un-acknowledged 2 mins. Water Tight Doors:#1 door Be to reduce. door oil leak from pump, #7 do pumping locally, # 23 door puntimes on the accumulator stored. VHF system very poor reception. # 9 lifeboat weathertight frame be Bulkhead area corroded near # 1. # 5 lifeboat falls rollers. 3 of 4. Lifeboat Davit limit switches: N. Shell doors: All four Main Deck nuts found to be wasting. Navigation deck aft, on open decand weld opening up. Lifeboat Rollers found seized: # all rollers. #6 allrollers. #7 for #10 both bottom sets. # 12 top the Lifeboat support pad leather covered. 	ips. This has cratips, 20mm x 3 of these blades. In the blade leads at damaged are funnel (previous and battery lock audible Fire / bulkhead slightly bor oil leak on ap switch box to pressure: # 10, a C deck port and bracket to repair 2 lifeboat Nav con aft fall not to 15 aft and Not door seal retains ck corner of supplies the bottom rollerward top set, afforward.	eated cavitation at the Omm, and thickness of Also damage noted or ling edge. Both thrusteas. It is also doubled in section ters on prom deck poor General alarm to repar buckled showing gather an outboard, # 11 doubled gain access. The form 14, 15 and 22. It is also deck companionway the arming, fwd fall top reasoning bolts, around outboard and aft not a forward and aft not gerstructure plastic raters, aft top aft. #2 all and aft top set. #8 all and aft top set.	e tips which has redown by 60% in the leading edgeter blades and product the blades and product and sun deck positive test. The profession of 3mm at center eck flap sticking, llowing doors did k port forward The investigate of the operating of the perimeter of the collers of the collection of t	esulted in the his area. The of forward peller blade. The gauged fort, to be mader of door, go with the doors. The doors of the doors of the doors. The doors of the doors.
	$\wedge \wedge$				
Surveyor's Sign	Name of Ship	Date	LR/IMO Number	Report Number	Page
	th	18.5.00	80004014	11 0 0 000151	

Surveyor's Signarus	Name of Ship	Date	LR/IMO Number	Report Number	Page	l
1 14	·	06.5.M				ļ
N.J. HASTINGS / A. MADDEN	NIEUW AMSTERDAM	10,2,00	80024014	VCR 000154	,	
11.3. TIASTINGS I A. INAUDEN			00024014	1 CK 000134	L *	3

- Lifeboat # 4 propeller blade bent and #2 exhaust pipe leaking.
- Crack in superstructure, outside cabin 88 to repair.
- Low location lighting emergency batteries expired 05/99 to renew as necessary.
- Skate missing from lifeboat #10 and aft skate twisted on #9 lifeboat.
- Galleys Wet chemical fire supression systems to be annually serviced & tested
- & location of instructions to be readily identifiable.
- Lido service area galley exhaust trunking to be cleaned & Main galley stbd.
- side hot plates centre inspection hatch blockage located in trunking to be
- removed.
- Lifeboats inventory/ renewals repairs as follows:
- # 1 Lifeboat Spare batteries.
- #2 Lifeboat 1 bucket, searchlight not working.
- #3 Lifeboat Spare batteries, compass binnacle glass cover to renew.
- #4 Lifeboat Engine instrument gauge panel to repair,
- #5 Lifeboat pyrotechnics to complete, No. of persons, fuel location etc to re-stencil., compass binnacle glass to renew, food packaging to dry.
- #7 Lifeboat Bilge pump not operating.
- # 9 Lifeboat weathertight frames to secure as necessary.
- #10 Lifeboat Engine instrument lines and gauge support broken, compass to refill.
- # 13 Tender Tool kit to rebuild, oil lamp wick not operating, 1 seat broken, CO@ bottle in eng compartment, bracket to refit.
- #14 Tender Engine Compartment lights to renew, insulation to refit above engines, CO2 bottle reconnect, wire loose and nozzle to fit, lever for hydraulic start to find, oil lamp wick not operatin
- #15 Tender Engine compartment CO2 brackets and nozzle to fit, insulation to refit above engin lamps in ER compartment to repair, new attery box to re-build.
- #16 Tender Bilge to clean, fishing gear to replace, spare bulbs for flashlight, light in engine compartment to repair.
- All lifeboats damaged TPA's packaging to renew & number allocation for each boat to be verified • All lifeboats - sea sickness bags to install.
- All lifeboats hull underside worn reflective tape to renew as necessary.
- All lifeboats three tin openers to supply to each boat.
- All lifeboats flashlight batteries to change.
- All lifeboats Small gear and TPA plastic boxes to be dried.
- Lifeboats number 6, 7, 8, 9, 10 and 11 lifeboats cracking of gelcoat found at mid-section on both sides. Boat builders to be consulted for repair.
- Damage Control Plan for vessel to find and verify.
- All childrens lifejackets to comply with SOLAS chapter III, sectII, Reg 32. Lights and whistles to
 - Water tight doors after general closure from the bridge: No indication from the bridge on the following doors due to fire damage: 15, 16, 23, 21 22 23 and doors 15, 16 and 23 only operationa by local and remote pump.
 - Lamp test button on Water Tight Door panel on the bridge not operational.
 - No 14 Lifeboat aft top roller seized and #12 Lifeboat forward falls swivel seized.
 - Officers bar starboard forward ceiling, fire insulation to replace prior to refitting ceiling panels.

Sury yor's Signature	Name of Ship	Date	LR/IMO Number	Report Number	Page
19/2/2007/1		201 -1			
A Carel A.	·	128.5.0			
N.J. HASTINGS / A. MADIJEN	NIEUW AMSTERDAM	- 0	80024014	VCR 000154	3

FORM 2112 R (05/95) LLOYD'S REGISTER OF SHIPPING

- Heat detector beside centre aft small engine, in main engine room, to refit, hanging loose.
- Extension lead in Housekeepers office found to have 220 volt plugs as well as 110 volt adaptor wit no transformer inbetween, cable destroyed.
- The following Draft Stops require insulation to be replaced: "A" Deck between cabin 556/558 and "B" Deck between cabin 678/682.
- Forward Promanade Deck large window outside shutters to be re-numbered on superstructure from to show which shutter fits what window.
- Navigation lights: Aft Top Masthead light switch on bridge panel to repair. It can only be used in a position, other position shorts out panel.
- Ballast panel in Boiler Room, 3 Port/Starb cross over tank valve, Number 2810, not operating.
- Lido Pool dumped, after 1 hr.20min pool still not empty. To investigate valve drainage sytem for blockage.

• Repairs/Renewals: Items completed

- Port side loadline markings painted.
- Lighting at: Funnel casing port side Boat deck & Bowthruster space re instated.
- Rope boxes aft mooring station stowed clear of fire dampers.
- Exposed electrical switch in Laundry, near Washex machine repaired.
- Low level lighting with sections out: cabin 414 to 416, cross alleyway by cabin 446, cabin 804 to 808, centre staircase to cabin 125, cabin 401 to 411, cabin 551 to 561, infront of service station B2 cabin 635 to 631, infront of cabin 627 and near WTD #3.
- Low level lighting: cover replaced on track by cabin 003, by store hds7 low power.
- Low location photoluminscent strips with direction markers replaced in B deck service corridor.
- Acetylene bottle removed from around fire hydrant & secure properly.
- All lifeboats Immersion suits dryed and all zippers tested and coatedwith beeswax.
- Steering gear space generally cleaned of hydraulic oil, rags now placed in containers Emergency lights re instated
- Manual fire damper MFD 35 Boat Deck freed (Eng. room fire dampers)
- deck forward port Water Tight Door pumping station oil cleaned from deck
- Machinery spaces- Plastic tubing oil tank level gauges removed/ changed to approved type.
- Spare tools removed from Boilers sand box.
- Bowthruster bilge pump now in operation.
- Bilge valves # 2763 indications repaired.
- Engine Room B Deck Service Corridor by BM10 FSD, Oxygen/Acetylene hoses being lead throug open pipe in Fire Zone Bulkhead to Engine room, now removed and caped.
- PA system: Crew area "A" deck aft officers quarters as well as cabin 612 and 554 now operation?
- B Deck Breakfast pantry hatch, cable penetration located in deckhead sealed.
- Remote starts of emergency bilge pump verify.
- Fire Screen Doors: B S2 hold back now working, S6 catching now working, N11 now latching and holding back
- Bilge valves # 2272 indication repaired.
- Flammable materials, batteries, Ox- Acet. gear, paint, grease drums removed from Fan room S1,S2,S3,S4 & S6 & areas cleaned as necessary.

Surveyor Sighature Name of Ship Date LR/IMO Number Report No	umber Page
1 10 10 10 10 10 10 10 10 10 10 10 10 10	
1 1 9 5 50 1	
N.J. HASTINGS / A. MADDEN NIEUW AMSTERDAM 80024014 VCR 000	154 4

- Exposed light fittings Store room H.D. B2, B deck now covered.
- Smoke detector in Laundry room Upper prom deck -exposed cables repaired.
- WTD remote station B deck hydraulic oil removed from deck & cleaned.
- Fire Screen Doors, indicator lights not showing shut during zone by zone test: Zone 4: S2, UPM4, DB4. Zone 3: M3, A5, M12. Zone 1: BM1. all now verified as working
- Paint Locker intrinsically safe lamp fitting ,secured.
- Main Show Lounge: Bingo Machine stored in front of starboard aft fire station, to remove.
- Fire screen doors:S5 to fast, S8 latch sticking and to fast, N4 to fast, N10 catching on floor and fast, BT10 not latching, P7 stay open lever not working, P8 not working, P13 glass door forwar of FSD covering handle(to discuss with C/O, M1 hinges twisted requiring fast closing to slam door shut, M3 not latching, M13 to fast, A2 frame cracking in top corner, A4 door frame loose and catching FSD, A9 hold open lever jammed, A11 to fast, A13 to fast and not holding back, A12 to fast and not latching, B3 to fast, B7 to fast, B9 hold open lever jammed, B13 to fast, B12 to fast an frame cracking top corner, B14 to fast, C3 and C4 hold open lever jammed, DB1 number to chan on door, DB4 to add to list stairwell to "Elevater Fwd of Laundry". All items completed
- Pursers Front Office: Steel fire screen shutters at desk now operational.
- Fan rooms Electrical panels indications/ running lights re instated.
- Lifeboat engine #12 repaired and tested, originally not running for more than a few seconds.
- Numerous Emergency lights on promanade deck repaired & Battery transitional discharge test agai carried out this time satisfactory. Port Aft liferaft station, outside light repaired.
- Store room P12 stock level reduce.
- Aft mooring deck fire shutters now unblocked.

*Delete as appropriate

Name of Ship	Date	LR/IMO Number	Report Number	Page
	70 .		·	1
NIEUW AMSTERDAM	18,2.00	80024014	VCR 000154	5
	Name of Ship NIEUW AMSTERDAM	78.500	78.5.00	78.5.00

·	Dynamic Carlo						926876150 ES.
	igenekaia	REPORTES TAS					H S N
j							
					-		
	·	ž.					
					•		
	,						
							·
							İ
	<u></u>						
Surveyor's Sign	abrel)	Name of Sh	ip	Date	LR/IMO Number	Report Number	Page

Surveyor's Signature Name of Ship	Date	LR/IMO Number	Report Number	Page
1 UT 1	28,00			
N.J. HASTINGS / A. MADDEN NIEUW AMSTERDAM		80024014	VCR 000154	6

77 - 14 M & M &	(GENERAL) REP	ORT LA	C. Militar			Maria Control
	·				•	
	•					
	•,					
						:
						•
		,				
				•		
<u> </u>		•				
	·					
						,
			•			
Surveyor's Sign	Anirė J	Name of Ship	Date	LR/IMO Number	Report Number	Page

Surveyor's Signature	Name of Ship	Date 9 R.C. D.	LR/IMO Number	Report Number	Page
N.J. HASTINGS / A MADDEN	NIEUW AMSTERDAM	60,200	80024014	VCR 000154	7

DEFINE A	GENERALIREP	ORIE SILVER ORIENTE				
						_
		•				
	T s				r	
	•					
	•					
		•			1	
.						
						•
				·		
		·			```	
			,			
	•					
Surveyor's Signatu	<i>Q</i>)	Name of Chi-	Data	I DO V		
Surveyor's Signatu	W	Name of Ship	Date 78'Y ON	LR/IMO Number	Report Number	Page
N.J. HASTINGS /	A. MADDEN		(U) (O)	80024014	VCR 000154	8

. .

destruction	NOTESCHARTSTRANGERSCHEIN LING BESCHEIN BESCHEIN STEIL GEGEN GEGEN GEGEN GEGEN GEGEN GEGEN GEGEN GEGEN GEGEN GE
ī.	SOLAS 1974/PROTOCOL 1978: The following is an extract from Chapter 1, Regulation 6 of the Protocol of 1978 Relating to the International Convention for the Safety of Life at Sea, 1974:
	"(d) When a nominated surveyor or recognised organisation determines that the condition of the ship or its equipment does not correspond substantially with the particulars of the certificate or is such that the ship is not fit to proceed to sea without danger to the ship, or persons on board, such surveyor or organisation shall immediately ensure that corrective action is taken and shall in due course notify the Administration. If such corrective action is not taken the relevant certificate should be withdrawn and the Administration shall be notified immediately. When an officer of the Administration, a nominated surveyor or recognised organisation has notified the appropriate authorities of the Port state, the Government of the Port State concerned shall give such officer, surveyor or recognised organisation any necessary assistance to carry out their obligations under this Regulation. When applicable, the Government of the Port State concerned shall ensure that the ship shall not sail until it can proceed to sea, or leave port for the purpose of proceeding to the appropriate repair yard, without danger to the ship or persons on board"
2.	SOLAS 1974 PROTOCOL 1988: An additional survey shall be held after the repair of a defect or replacement or renewal of equipment which affects the safety of a ship or the completeness of its life saving appliances or other equipment. Such repairs, replacements or renewals are required to be reported by the Master to the organisation responsible for the issue of the relevant certificate, in order that an additional survey may be held if considered necessary.
3.	SOLAS 1974 PROTOCOL 1978: The following is an extract from Chapter I Regulation 14 of the Protocol of 1978 relating to the International Convention for the Safety of Life at Sea 1974;
	"(d) If the ship at the time when a certificate other than that referred to in paragraph (b) of this regulation, expires is not in a port of the State whose flag it is entitled to fly or in which it is to be surveyed, the Administration may extend the certificate, but such an extension shall be granted only for the purpose of allowing the ship to complete its voyage to the State whose flag it is entitled to fly or in which it is to be surveyed, and then only in cases where it appears proper and reasonable to do so."
4.	GENERAL Every effort must be made to complete the survey in one operation but, if this cannot be achieved due to lack of facilities or other justifiable reason and only items of a minor nature are outstanding, arrangements should be made for the survey to be completed at the next port. Full particulars should be left on board and the surveyors at the next port advised accordingly. The Attachment/Supplement/Certificate should not be endorsed until the survey has been entirely completed.
5 .	For arrangement and disposition of safety equipment see 'Record of Approved Passenger Ship Safety Equipment' (Form 2114) and relevant safety plans.
6.	All requests for extensions to the Passenger Ship Safety Certificates are to be referred to CSD/SAS/PASS for advice. (See note 3 above).
7.	At an in Water survey, the rudder pintle upper stock bearing and tailshaft clearances are to be measured, unless the design precludes this.
•	All requests from Owners to hold an under water examination in lieu of dry docking should be referred to CSD/SAS/PASS for advice before the survey is held.
8.	Nautical publications consist of up-to-date charts, sailing directions, list of lights, Notices to Mariners, tide tables and all other nautical publications necessary for the intended voyage.

	•			
Name of Ship	Date	LR/IMO Number	Report Number	Page
i i	1000	ŀ	'	
	124.5.30			
NIEUW AMSTERDAM		80024014	VCR 000154	١٩
	Name of Ship NIEUW AMSTERDAM	28.5.30	28.5.30	28.5.30

SURVEY CHECK LIST

(TO BE ATTACHED TO THE SURVEY REPORT AT ALL TIMES). SEE BELOW FOR ASSOCIATED REPORT NUMBER

SURVEY REQUIREMENTS FOR ALL PASSENGER SHIPS

NIEUW AMSTERDAM

FORM 2112 R (05/95) LLOYD'S REGISTER OF SHIPPING

Mark 'X' or '-' to indicate 'YES' or 'NO' in appropriate box for each item. If an item is not applicable mark 'NA' in appropriate box. All required dates should be recorded at all Surveys.

NOTES

- 1. Each lifeboat is required to be taunched and maneuvered at least once every 3 months.
- 2. Renewal required when necessary but at intervals not exceeding 5 years. Reversal end for end required at intervals not exceeding 30 months.

	AVE WEST	GEN	ERAL SA								en de la	
	A .1		Has any changes been made or new equipment been installed which would affect the validity of the Passenger Ship Safety Equipment Certificate?									
		(Any modifications to be reported and certificates forwarded if necessary) Yes							Yes		No x	
7	A.2)	All ins	tructions and /or	notices including the emergen	cy Sta	ntion Muster List	and To	raining Manual wer	·e			x
^	3	posted	or available in t	he appropriate language as requ	uired a	and to the Master	r's sati:	sfaction				
	A3/	All oth	er Statutory Cer	tificates and the Class Certifica	ate we	re valid at the tir	ne of s	urvey				x
				List the following:				Expiry Date	Endors	ement Date	Certifical	e Issued by
	(a)	Interna	tional Load Line	: Certificate			01.0	6.98			01.06.03	
	(b)	Interna	tional Oil Pollut	ion Prevention Certificate			25.0	5.99			01.06.035	
	(c)		tional Pollution I Substances in Be	Prevention Certificate for the Culk	Carria	ge of Noxious		,				
	(d)	Classif	ication				30.0	5.03	<u></u>		31.05.98	
	A.4	Are CS	SH/CSM Survey	cycles up-to-date						Yes X		No ·
	3 1.5	Are the	surveys of Boil	ers and other pressure vessels	up-to-	date				Yes X		No 🖸
	<u>^</u>			nd Crew certificated as require nkeeping Convention	d by S	Standards of Trai	ining					x
	\mathbf{A}	Ships c	complement com	plies with Minimum Safe Mani	ning I	Document (SOLA	S 74/7	8 R V/13 (b))				x
	A.8	the port	-	any fire necessitating the opera shers, since the last Passenger St General Report)			xtingui	shing systems or		Yes X		No 🕒
ì		Signal Control	(a) (a) (a)			itala serenan	* 6				BA CASARATA	time services
	B.I	No No	UMENTAT	Plan		Vo. Required	57 2054	io. On Board	Charles and a	Where Di	filition!	
		Fire Control* or Emergency Booklet (SOLAS 74/88 R II-2/20)			2		5	B Deck Serv D Deck near	ar Emergency G ice Alleyway Water Tight D Crew Staircase	ienerator Roc oor 17	om	
							· .					
1	*Duplicate of plan Surveyor's Signs		ergency Booklet	to be available in a prominent Name of Ship	mark	ed enclosure exte	rnal to	the Ships deckhou LR/IMO Numbe		4/88 R-II-2/20) Report Numl	ber	Page
į	22. 10,01 a bigin		'	······································		78.50	, l		•	sopost Hulls	~··	. 450

80024014

VCR 000154

No	Plan	No. Required	No. On Board	Where Displayed
2	Damage Control and Damage Control Booklet (SOLAS 74/88 R-II-1/23)	1	0	Not On Board
	•.			
3	Life Saving Plans	•	8	Boat Deck across from Emergency Generator Room A Deck Officers Cross alleyway
	4			A Deck starboard near Engine Control Room B Deck Service Alleyway Aft
				B Deck near Cabins B4/B5 D Deck near Cabins D81/D98
				D Deck near Crew Cabins D46/D39
				Fire safety booklets in:
				Shell Door Areas Officers Cabins
				Bridge
				Engine Control Room
4	Capacity and Deadweight Scale	1	2	Bridge
				Emergency Hospital located behind Bridge
5	Hydrostatic Curves	1	1	Bridge locker near GMDSS station
6	Trim and Stability Manual (SOLAS 74/88 R-II-1/22)	1	1	Bridge locker near GMDSS Station
7	Guidance notes to Master	1	1	Masters Cabin
8	Muster List and Emergency Instructions		8	Emergency Hospital located behind Bridge Boatdeck near Emergency Generator Room A Deck cross alleyway in Officers Accomadation A Deck starboard near Engine Control Room
				B Deck service alleyway near Fanroom B1 B Deck near Cabin B4/B5 D Deck near Watertight Door 17 D Deck near Crew Cabin D46/D39
9	Load Line Certificate	, 1	1	Certificate Box on the Bridge
10	Permanent Ballast Plan	1	1	Bridge Portside "Tank Arrangements"
11	Passenger Safety Certificate and Record of Equipment for the Passenger Ship Safety Certificate (Form P)	1	1 .	Certificate Box on Bridge
12	Record of Passenger Ship Safety Equipment	1	1	Certificate Box on Bridge
13	Passenger Safety Survey Report	1	1	Certificate Box on Bridge
14	Addendum for Carriage of Dangerous Goods (SOLAS 74/88 R II-2/54 + R VIII/5)			N/A
	Nautical Publications* (SOLAS 74/88 R/20)	1 each	1 each	Bridge Locker under GMDSS Station
Surveyor's SignAure	Name of Ship	Date	LR/IMO Numbe	er Report Number Page
N.J. HASTINGS	MADDEN NIEUW AMSTERDAM LOYD'S REGISTER OF SHIPPING	28.5.00	80024014	VCR 000154 11

	16	International Code of Signals	1	1	Bridge Starboard Side		
	İ	,					
	17	Training Manual (SOLAS 74/88 R III/51)		4	Bridge Crewmess Petty Officers Bar Officers Bar		
	18	Instructions for on board maintenance			Bridge, AMOS-D Computer system		
		(SOLAS 74/88 R III/52)			Engine Control Room, AMOS-D Computer system		
:	19	Maneuvering booklet and information displayed on bridge (SOLAS 74/88 R-II-1/28)	. 1	1	Bridge Portside wall and in binder		
	20	Radar Shadow Sectors (SOLAS 74/88 R V/12)	•	1	Bridge on wall behind Chart Table		

$\mathcal{L}_{\mathcal{L}}$			•		
Surveyor's Signature	Name of Ship	Date	LR/IMO Number	Report Number	Page
e p		28.5.50			
N.J. HASTINGS A. MADDEN	NIEUW AMSTERDAM		80024014	VCR 000154	1 12

	21	Operational and Maintenance manuals for navigational equipment (SOLAS 74/88 R V/12) (See note 8, page 2 of report	·	1	Bridge Portside locker	
						. •
					•	
B.2	Radio	Survey held and survey Checklist (Form 2137) f	orwarded			X
B.3	Log be	ook entries being made for the following:-				
B.3.1	Date w	hen last full muster of passengers and crew for l	boat and fire drill too	ok place (prior to this sur	vey)	
B.3.2		S 74/88 R III/18 + 19)		_dd/mm/yy Crew S 74/88 R III/18 + 19)	v 14.05.00	[X]
			-			_
B.3.3		ecasion lifeboats were swung out and when each umbers and dates (prior to this survey) (SOLAS)			14.05.00 Port	X
B.3.4	Crew	nembers have received appropriate onboard train	ning. (SOLAS 74/78	R III/18 + 19)		x
B.3.5	i	d the person in charge of survival craft and in th survival craft crew.	e case of lifeboats th	e second in command hav	ve a list	X
B.4	- 1	aware of intent of SOLAS 74/78 R II-2/22 'In a	•		kept in	x
B.5	Other	og book entries required by SOLAS 1974 as am	ended for the follow	ing:-		•
B.5.1	Openir	ig, closing and locking of side scuttles below ma	rgin line (SOLAS 74	/78 R-II-1/17)		X
B.5.2	<u>i</u>	e of cargo loading doors and closing of any door king or disembarking of passengers (SOLAS 74/	•	operation of the ship at the	ne	x
B.5.3	Openia	igs required to be kept closed at sea being kept c	losed. (SOLAS 74/8	8 R-II-1/24/25)		X
B.5.4	Requir	ed drills and inspections of watertight doors are	being carried out. (S	SOLAS 74/88 R-II-1/24/2		х
B.5.5	Testing	and emergency drills of steering gear. (SOLA	S 74/88 R V/19)			x
B-5.6		ecasion rescue boat was launched and maneuvere in launchings and maneuverings not to exceed 3	• •	•	interval	⊡

[7]					
Surveyor's Signature	Name of Ship	Date	LR/IMO Number	Report Number	Page
	ì	78.5.00			
N.J. HASTINGS / A. MADDEN	NIEUW AMSTERDAM	20.3.00	80024014	VCR 000154	13

CTUP!	SWATEREIGHTEINTEGREDY: 12 12 12 12 12 12 12 12 12 12 12 12 12	
	THE FOLLOWING FOUND IN SATISFACTORY CONDITION	
C.1	Outside of ships bottom (including bottom and bow plating, keel, bilge keels, stern, stern frame rudder chests and strainers. (SOLAS 74/88 RI/7(b)(ii))	х
C.2	Propeller and shaft seals. (SOLAS 74/88 R I/7 (b) (ii))	
C.3	Rudder bearing clearances measured. (SOLAS 74/88 R L/7(b)(ii) (see note 7 page 2 of report) (Give clearances)	•
C.4	Propeller shaft clearances (SOLAS 74/88 RI/7 (b)(ii) (see note 7 of page 2 of report) (Give clearances)	⊡
ADZ SANSE	BALLAST STOWAGE (SOBAST/4/88 III 1/9) A BARBARI (A DE SECONDE LA DESERVACIONES DE DESERVACIONES DE LA DESERVACIONES DE LA DESERVACIONES DE LA DESERVACIONES DE LA DESERVACIONES DE LA DESERVACIONES DEL DESERVACIONES DE LA DESERVACIONES DEL DESERVACIONES DE LA DESERVACIONES DEL DESERVACIONES DE LA DESERVACIONES DE LA DESERVACIONES DE LA DESERVACIONES DEL DEL DEL DEL DEL DEL DEL DEL DEL DEL	
D.1	Solid Ballast stowed per plan.	
D.2	Permanent liquid ballast stowed per plan.	
D.3	Ballast arrangements verified.	×
E L	WATERUIGHTEBULKHEADS (SOLAS VAISSIR) ILIVIONERS (SIS)	
E.1	Integrity of all sub-division watertight bulkheads (including in way of pipe, cable penetrations, etc.) verified.	x
E.2	Remote controls for bulkhead isolation valves on the bilge, black and grey water systems operated and open/closed indication verified.	<u> </u>
	WATERTIGHT DOORS (SOLAS VAISSIR ILLIVIS) (See 1) 10 20 20 20 20 20 20 20 20 20 20 20 20 20	
F.I	Doors closed from Bridge and locally from both sides of bulkhead	
F.2	Position of control handles such that both handles can be held open simultaneously in the open position	x
F.3	Indicators on Bridge and other remote operation position and alarms (both audible and where necessary visual) at doors verified	
F.4	Doors closed from above bulkhead deck by hand	×
F.5	Doors operated locally by hand	x
F.6	Diagram on bridge showing location of WT doors verified	x
F.7	Operating notices on non-remotely controlled watertight doors verified	⊡
	PORTABLE PLATESUSOLAS JUSB RITHLISTE CONTROL OF THE STATE	
The second second second second		
G 1	Portable plates, manhole covers, etc., verified closed	
G.1 G.2		x
G.1	Portable plates, manhole covers, etc., verified closed	
G.1 G.2	Portable plates, manhole covers, etc., verified closed Notices affixed thereto verified	x
G.1	Portable plates, manhole covers, etc., verified closed Notices affixed thereto verified	x

.

\mathbf{H}_{i}	SHELD OPENING (SOLAS 74/88)RUL WIN DEPARTMENT OF THE PROPERTY	新发现的过去式
Н.1	Ship's side doors examined and verified tight	×
н.2	Non-opening and key operable sidelights verified	x
Н.3	Deadlights and window shutters verified	x
H.4	Galley chute verified closeable tight	х
н.5	Scupper, sanitary and other discharge shell valves and their remote control verified	х
Н.6	Indicators on Bridge showing all shell openings are closed verified	x
Н.7	Means to detect water leakage through shell opening verified. (SOLAS 74/88 R II-1/23/2)	
Н.8	Sea inlet valves verified accessible and fitted with status indicator	x
H.9	Drainage from Special Category spaces verified efficient. (SOLAS 74/88 R II-1/21)	⊡
H.10	Sewage tank arrangement including overboard discharge arrangement verified	x
	<u></u>	
1,145,000	WATERTIGHT INTEGRITY ABOVE THE MARGINIEINE (SQUASTA/88)R (151/20)	59.040 +1-11 "
1.1	Partial watertight bulkheads on bulkhead deck verified	×
1.2	Weathertight closure of all openings on all weather decks verified	×
1,3	Freeing Ports verified	x
	BILGE PUMPING (SOLASIZA/888RIII-1/21)	andial ass.
J.1	All pumps operated	x
1.2	Remote starting operated	x
1.3	Remote controls for valve chests, etc., operated	x
K. Lipitalia	SOUNDING PIPES	***
K.1	Lever weighted cocks in machinery spaces verified	x
K.2	Flush deck type in accommodation, etc., verified accessible	×

		·			
Surveyor's Signature	Name of Ship	Date	LR/IMO Number	Report Number	Page
		28.5.8			
N.J. HASTINGS A. MADDEN	NIEUW AMSTERDAM	10 2-00	80024014	VCR 000154	15

Remote sounding devices verified

K.3

ASSESSED AND ADDRESSED	CROSSMEVELING IDUMPING ARRANGEMENTS (SOMAS 54/88 PRITE 18) 15 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2				
L.i	Swimming pool emptied and time checked				
L.2	Cross-flooding arrangement verified	×			
L.3	Blow-out plugs verified				
L.4	Down flooding arrangement verified	x			
L.5	Stabilizer dump system verified				
	•				
Marsa and	DOADIDINE AND DRAUGHTIMARKS (SOLAS 74/88 IR JL 1/8)	李洁的			
M.1	Load line marks verified and repainted if necessary Freeboard = 2880 mm	x			
M.2	Draught marks or reliable indicating system confirmed	x			
		ASS TO A CORPORA			
Nu partirio	STABILITY AND OPERATING PRACTICE (SOLAS VA/88 RILLEYS) & CHARLES AND A COLOR OF THE				
N.1	Approved stability/loading information onboard (Date of approval: 08.11.99)	x			
N.2	Vessel stated being operated in accordance with Master's Stability Instructions	x			
io.vta in	MAGHINERY AND STEERING GEAR AND STEERING AND	ing a state of			
0.1	Maintenance of machinery, boilers and other pressure vessels, associated piping system and fittings to				
	minimise any danger due to moving parts, hot surfaces and other hazards verified (SOLAS 74/88 R II-1/26)	x			
0.2	Normal operation of propulsion machinery being sustained or restored in the event of one essential auxiliary becoming inoperative verified (SOLAS 74/88 R II-1/26)	. x			
0.3	Means to bring machinery into operation from dead ship condition without external aid verified (SOLAS 74/88 R II-1/26)	х			
0.4	Means to protect against overpressure in main, auxiliary and other machinery verified (SOLAS 74/88 R II-1/27)	х			
0.5	Crankcase explosion relief devices verified (SOLAS 74/88 R II-1/27)	х			
0.6	Maintenance of automatic shutoff arrangements fitted to main and auxiliary machinery verified (SOLAS 74/88 R II-1/27)	х			
0.7	Means to reverse thrust of propeller(s) verified (SOLAS 74/88 R II-1/28)	x			
0.8	Maintenance of main and auxiliary steering gear confirmed (SOLAS 74/88 RR II-1/29)	x			
0.9	Arrangements to ensure that failure of either the main or auxiliary steering gear does not render the other inoperable verified (SOLAS 74/88 R II-1/29)	x			
O.10	Auxiliary steering gear capable of being brought speedily into action in emergency (SOLAS 74/88 R II-1/29)	x			
0.11	Lubrication arrangements for essential components of steering gear verified (SOLAS 74/88 R II-1/29)				
0.12	Relief valves in steering gear hydraulic system stated to be set to correct pressure? (SOLAS 74/88 R II-1/29)				
0.13	Automatic restart of main and auxiliary steering gear power units following power failure (SOLAS 74/88 R II-1/9)				
Surveyor's Signs		Page			
	A. MADDEN NIEUW AMSTERDAM 80024014 VCR 000154	16			
FUKM 2112 K (05	7951 CLOYD'S REGISTER OF SHIPPING				

O.14	Capability of main and auxiliary steering gear being started from bridge confirmed (SOLAS 74/88 R II-1/29)	x
0.15	Available and visual alarms on bridge indicating poor failure of any one steering gear verified (SOLAS 74/88 R II-1/29)	x
0.16	Control systems from bridge and steering gear room for main steering gear verified (SOLAS 74/88 R II-1/29)	x
0.17	Where auxiliary steering gear is not fitted operation of the two independent control systems from the bridge for the main steering gear power units verified (SOLAS 74/88 R II-1/29)	⊡
O.18	Operation of control system for auxiliary steering gear in the steering gear compartment and if power operated from the bridge verified (SOLAS 74/88 R II-1/29)	x
O.19	Bridge control for auxiliary steering gear (if fitted) verified independent of main steering gear control system (SOLAS 74/88 R II-1/29)	x
0.20	Audible and visual alarm on bridge indicating failure of electrical power verified (SOLAS 74/88 R II-1/29)	x
0.21	Communication between bridge and steering gear verified (SOLAS 74/88 R II-1/29)	x
0.22	If provided with emergency steering position communication to relay heading information and visual compass readings verified (SOLAS 74/88 R V/12)	x
0.23	Independent rudder angle indicator on bridge verified (SOLAS 74/88 R II-1/29)	x
O.24	Rudder angle indicator in steering gear room verified (SOLAS 74/88 R V/12)	x
0.25	Audible and visual low level alarms for hydraulic steering gear on bridge and in machinery space verified (SOLAS 74/88 R II-1/29)	x
O.26	Means to recharge one hydraulic actuation system from a storage tank (with fixed contents gauge) in steering gear compartment verified (SOLAS 74/88 R II-1/29)	x
0.27	Ready accessibility of steering gear compartment verified (SOLAS 74/88 R II-1/29)	x
O.28	Arrangements to ensure safe working access to steering gear machinery and control verified (SOLAS 74/88 R II-1/29)	x
0.29	For electric or electro hydraulic steering gear indication on bridge and ECR that motors are running verified (SOLAS 74/88 R II-1/30)	x
0.30	Overload alarm and loss of phase alarm for three phase supply in ECR verified (SOLAS 74/88 R II-1/30)	x
0.31	Maintenance of means of control and main and auxiliary machinery for propulsion and the safety of the ship (SOLAS 74/88 R II-1/31) (according to Chief Engineer's Records)	x
0.32	If fitted means for remotely controlling the propulsion machinery from the bridge verified (SOLAS 74/88 R II-1/31)	x
0.33	Arrangements to operate main and other machinery from the machinery control room verified (SOLAS 74/88 R II-1/31)	x
0.34	Maintenance of means for manually overriding automatic controls and their failure does not prevent the use of the manual override verified (SOLAS 74/88 R II-1/31)	x
O.35	Safety features fitted oil fired and exhaust gas boilers, unfired steam generators, steam pipe systems and air pipe systems and air pressure systems verified (SOLAS 74/88 R II-1,32, 33, 34)	x
O.36	Machinery space ventilation operated satisfactorily (SOLAS 74/88 R II-1/35)	x
0.37	Noise prevention measures in machinery spaces verified (SOLAS 74/88 R II-1/36)	x

Surveyor's Signature	Name of Ship	Date	LR/IMO Number	Report Number	Page
I IXI		78.50m			
N.J. HASTINGS LA. MADDEN	NIEUW AMSTERDAM	C0 1,00	80024014	VCR 000154	17

O.38	Operation of engine room telegraph giving visual indication of orders and answers in the machinery spaces and bridge confirmed satisfactory (SOLAS 74/88 R II-1/37)		x			
O.39	Second means of communication between navigation bridge and machinery space (including any other engine control position) verified (SOLAS 74/88 R II-1/37)		x			
0.40	Audibility of Engineers' alarm in engineers' accommodation verified (SOLAS 74/88 R II-1/38)		х			
0.41	Precautions to prevent oil escaping under pressure coming into contact with heated surface verified (SOLAS 74/88 R II-2/15)					
0.42	Means to prevent over pressure in oil tanks and the oil system verified (SOLAS 74/88 R II-2/15)		x			
P/9/201/2	ELECTRICAL INSTALLATION: SPING NO. 100 ACCURATE AND ACCUR					
P.1	. 20% of the Electrical installation megger tested (SOLAS 74/88 II-1/40, 41)		[x]			
P.2	Emergency generator operated to test load and starting methods verified (SOLAS 74/88 II-1/42, 44)					
P.3	Emergency battery capacity verified, by discharge test (SOLAS 74/88 II-1/42)		×			
P.4	Precautions against shock, fire and other electrical hazards (SOLAS 74/88 II-1/45)		×			
P.5	Arrangements for unattended machinery spaces (if fitted) (SOLAS 74/88 II-1/54)		<u> </u>			
P.6	Supplementary emergency lighting satisfactorily tested & disposition verified (SOLAS 74/88 II-1/42-1)		<u> </u>			
07.25%	PUMPSS FIREMAIN HYDRANTS THOSESTETC SCOUAS 74/88 PULZ (4 19) FOR SECOND	then someth	rozach so			
Q.1	Fire pumps capable of producing the required two jets of water		x			
Q.2	All pumps, fire main, hydrants, hoses, nozzles, applicators, spanners, relief valves and international shore connection were in good condition		. X			
Q.3	Each hose complete with couplings, nozzle and tools kept ready for use		x			
Q.4	Long handled water fog applicators stowed as required (SOLAS 74/88 R II-2/7, 17, 27)		x			
RVACES IN	PORTABLE EXTUNGUISHERS (SOLAS 7/4/88 RULZ/6) (7) L. S. C.	lle assikar e s				
R.1	All extinguishers fully charged and in their stowed position		x			
R.2	Date when charged	ous 8/98 to 03/0				
R.3	In each boiler firing space		.			
	sand in box with scope, OR		x			
R.4	an approved portable extinguisher provided		x			
R.5	Spare charge for each extinguisher other than for gas cylinder was provided		x			
R.6	Spare gas cylinders provided		x			
R.7	All extinguishers in their stowed positions and a random check revealed no discharge containers		$\overline{\mathbf{x}}$			
R.8	Date cylinders pressure tested Vario	ous 03/97 to 03				
	10					
Surveyor's Signa		Number	Page			
N.J. HASTINGS		0154	18			
FORM 2112 R (05	5/95) LLOYD'S REGISTER OF SHIPPING					

	MON-PORTABUESE XITING	IISHERS AND	IFOANTAPPLICATIO	RI(60E/AS#/4/88#RIII-2	<i>(</i> 6,17)	V10
S.1	Each extinguisher and foam applicator t	ınit was fully charge	ed and in its stowed position			X
S.2	Date when charged	Extinguishers	08/98 to 01/00	Applicator Units	4/96, 01/00	
S.3	Date when pressure tested			Various	04/97	

	Location	Indicate type of system fitted
T.1	Engine Room	C02
T.2	Boiler Room	CO2
T.3	Pump Room	. •
T.4	Dry cargo spaces	•
T.5	Accommodation spaces	
T.6	Galley exhaust ducts	WET CHEMICAL
T.7	Other spaces as on record	PANTRIES - HI FOG. GALLEY - HALON.
Т.8	1 '	, piping and nozzles found in good condition and clear of ating satisfactorily and means of operation clearly marked

104. (1941)	CO; SYSTEM (COLAS#A/88R) II-2/5)	
U.I	Date container(s) contents verified	28/03/00
U 2	Date container(s) pressure tested	9/96, 4/98
U.3	Date system last serviced	28/03/00 .
U.4	System examined and tested as far as practicable and found satisfactory	x
U.5	Means for closing all openings to protected space and stopping of boiler fans, fuel pumps, etc. verified	x
U.6	Operating instructions verified	· x

/.1	Date container(s) contents verified	03/05/00
7.2	Date container(s) pressure tested	4/96
7.3	Date system last serviced	0/05/00
7.4	Systems examined and tested as far as practicable and found satisfactory	x
1.5	Operating instructions verified	[x]

$\mathcal{L}/1$		·			
Surveyor's Signature	Name of Ship	Date	LR/IMO Number	Report Number	Page
1 (4)		28.5.3			
N.J. HASTINGS / A. MADDEN	NIEUW AMSTERDAM	C8.7.20	80024014	VCR 000154	19

W-1 - Activ	FOAM SYSTEM(S) P(SOLAS 73/88 RM 2/0) X CERT FOR THE FORM SYSTEM STATES FOR THE FORM SYSTEM STATES FOR THE FORM SYSTEM STATES FOR THE FORM SYSTEM STATES FOR THE FORM SYSTEM STATES FOR THE FORM SYSTEM STATES FOR THE FORM SYSTEM STATES FOR THE FORM SYSTEM STATES FOR THE FORM SYSTEM STATES FOR THE FORM SYSTEM STATES FOR THE FORM SYSTEM STATES FOR THE FORM SYSTEM STATES FOR THE FORM SYSTEM STATES FOR THE FORM SYSTEM STATES FOR THE FORM SYSTEM STATES FOR THE FORM SYSTEM STATES FOR THE FORM SYSTEM SYSTEM SYSTEM STATES FOR THE FORM SYSTEM SYST	
W.1	Date foam sample tested	<u> </u>
W.2	Systems examined and tested as far as practicable and found satisfactory	<u> </u>
X: 1953	FIREDOORS IN: ANAND ABYOLASSIDIVISIONS (SODAS 74/88) R-II 2/80/81)	P-0-5-0k-3/4 - 3-1
X.1	'Held open' types, Bridge operation, operated from Bridge and locally	X
X.2	'Continuous use' types, local operation, operated	х
X.3	'Permanently closed' types, local operation, operated	x
X.4	All doors clear and unobstructed and in good condition	x
War in se	EVENUTION (SOPAS 74788) RMI 2/1/31 (16,32 BV)	ing galactic
Y.1	Accommodation shut-downs operated	x
Y.2	Machinery shut-downs operated	x
Y.3	Special category space shut-downs operated	⊡
Y.4	Machinery flaps and vent closed	x
Y.5	Engine Room skylights closed from inside and out	
Y.6	Weather deck dampers and closing appliances for inlets/outlets operated	x ·
Y.7	Fan room dampers operated	· 💌
Y.8	A/C and ventilation dampers operated both sides manually	
Y.9	A/C and ventilation fusible links inspected	
Y.10	Galley vent cleaning access verified	
Y.11	Fixed fire extinguishing in galley exhaust vent verified and/or serviced	x
Y.12	Access and labeling of all dampers	
Y.13	Additional machinery space arrangements boiler forced and induced fan shut-downs operated	<u> </u>
7	OIL RUBE QUICK SHUTDOWNSE (SOLAS 7/4/88 RITE 2/11/1/15)	
Z.1		
	Operated satisfactorily for tanks containing oil fuel, lubricating oil and other flammable oils	<u> </u>
Z.2	Oil fuel and other flammable liquid pump shut down operated	x

Surveyor's Signature	Name of Ship	Date	LR/IMO Number	Report Number	Page
alpi		7K. C. 8x			
N.J. HASTINGS / STANDDEN	NIEUW AMSTERDAM	100.2.00	80024014	VCR 000154	20

AAC .	SPRINKTIER SYSTEM (SOEAS#4788)RUE-2/12/#36) FOLD FOLD FOR FOR FOR FOR FOR FOR FOR FOR FOR FOR	
AA.1	Auto-start of pump tested with discharge open	
AA.2	Tank pressure relief valve checked	
AA.3	Zone test valves operated and checked with panel on Bridge	
AA.4	Visual and audible alarm activated whenever system operated	
AA.5	Condition of sprinkler heads	
AA.6	Spare heads available (6 per section)	⊡
AA.7	Shore and fire main connections verified	
AA.8	Zone plan provided at each section station	
<u> </u>		
BB: 3 3	FIREMAN OUTFITS (SOEAS 74/88)R4[[2/17]] ***********************************	16 3 ()
BB.1	Each unit complete, in good condition and store per Form 2114	×
BB.2	Each outfit complete with air cylinders, including spare cylinders, fully charged	×
BB.3	Air compressor (if fitted) operated satisfactorily	x
BB.4	Smoke mask, air pump and hose tested and found satisfactory	
BB.5	Long handled applicators stowed at each fire station	x
TOTAL STATE OF	BUIDDUNGUISATIONE/COLACE/ACCIDIDATE/OFFICE COLOCACE/ACCIDIDATE/COLOCACE/ACCIDIDATE/OFFICE COLOCACE/ACCIDIDATE/OFFICE COLOCACE/ACCIDIDATE/	aranaan
(6C4) (25a) (5	SHIRESINSULFATIONS (SOLAS 74/88/R3112/23/TO/85)	
CC.1	FIRE INSULATION (SOLAS 14/888 R 1132/23 (10/85)) Fire insulation in good condition and in accordance with approved plan (including openings in 'A' and 'B' class divisions, ventilation systems, windows and side scuttles and the use of combustible material).	
CC.1	Fire insulation in good condition and in accordance with approved plan (including openings in 'A' and 'B' class divisions, ventilation systems, windows and side scuttles and the use of combustible material).	
CC.1	Fire insulation in good condition and in accordance with approved plan (including openings in 'A' and 'B' class divisions, ventilation systems, windows and side scuttles and the use of combustible material). **DRAFTESTOPS**SMOKETHOLES**ETG**(SOVASVA/88 RUL2/35)	
DD.	Fire insulation in good condition and in accordance with approved plan (including openings in 'A' and 'B' class divisions, ventilation systems, windows and side scuttles and the use of combustible material). DRAFT-STOPS: SMOKEHOLES: ETG: (SOIAS: 14/88 RIII 2/35)	
DD DD.1	Fire insulation in good condition and in accordance with approved plan (including openings in 'A' and 'B' class divisions, ventilation systems, windows and side scuttles and the use of combustible material). DRAFT-STOPS: SMOKEHOLES: ETGS (SDIAS) 4/88 R112/35) Draft stops behind linings, etc. verified Smoke holes verified	
DD.	Fire insulation in good condition and in accordance with approved plan (including openings in 'A' and 'B' class divisions, ventilation systems, windows and side scuttles and the use of combustible material). DRAFT-STOPS: SMOKEHOLES: ETG: (SOIAS: 14/88 RIII 2/35)	
DD DD.1	Fire insulation in good condition and in accordance with approved plan (including openings in 'A' and 'B' class divisions, ventilation systems, windows and side scuttles and the use of combustible material). DRAFT-STOPS: SMOKEHOLES: ETGS (SDIAS) 4/88 R112/35) Draft stops behind linings, etc. verified Smoke holes verified	
DD.1 DD.2 DD.3	Fire insulation in good condition and in accordance with approved plan (including openings in 'A' and 'B' class divisions, ventilation systems, windows and side scuttles and the use of combustible material). DRAFT-STOPS, SMOKETHOLES, ETG. (SOIASW4/88 RIL2/35) Draft stops behind linings, etc. verified Smoke holes verified All machinery rooms, bilge's, etc., clear of oil and other high fire risk materials	
DD.1 DD.2 DD.3	Fire insulation in good condition and in accordance with approved plan (including openings in 'A' and 'B' class divisions, ventilation systems, windows and side scuttles and the use of combustible material). DRAFT STOPS SMORE HOLES FTG (SOLAS V4/88 R III 2/35) Draft stops behind linings, etc. verified Smoke holes verified All machinery rooms, bilge's, etc., clear of oil and other high fire risk materials MEANS OF ESCAPE (SOLAS V4/88 R III 2/28) Stairways and ladders providing means of escape to lifeboat and life raft embarkation deck(s) from all passenger	
DD.1 DD.2 DD.3	Fire insulation in good condition and in accordance with approved plan (including openings in 'A' and 'B' class divisions, ventilation systems, windows and side scuttles and the use of combustible material). DRAPT-STOPS SMOREHOLES ET (\$\sum_{\text{CM}}(\text{SOLASTA/88 RML2/35})) Draft stops behind linings, etc. verified Smoke holes verified All machinery rooms, bilge's, etc., clear of oil and other high fire risk materials MEANS OF ESCAPE (\$\sum_{\text{SOLASTA/88}}(\text{RML2/28}) \) Stairways and ladders providing means of escape to lifeboat and life raft embarkation deck(s) from all passenger and crew spaces and other spaces where crew normally employed confirmed.	x
DD.1 DD.2 DD.3 EE1 EE.1	Fire insulation in good condition and in accordance with approved plan (including openings in 'A' and 'B' class divisions, ventilation systems, windows and side scuttles and the use of combustible material). DRAPLESTOPS, SMOKEHOLES, ETGE (SOLAS) (4/88 RILL2/35) Draft stops behind linings, etc. verified Smoke holes verified All machinery rooms, bilge's, etc., clear of oil and other high fire risk materials MEANS OF ESCAPE (SOLAS (74/88 RILL2/28)) Stairways and ladders providing means of escape to lifeboat and life raft embarkation deck(s) from all passenger and crew spaces and other spaces where crew normally employed confirmed. Means of escape from special category spaces confirmed	x
DD.1 DD.2 DD.3 EE.1 EE.2 EE.3 EE.4	Fire insulation in good condition and in accordance with approved plan (including openings in 'A' and 'B' class divisions, ventilation systems, windows and side scuttles and the use of combustible material). DRAFFSTOPS: SMOKEHHOLES, BETGA (SOLAS) (A/88 RH (12/35)) Draft stops behind linings, etc. verified Smoke holes verified All machinery rooms, bilge's, etc., clear of oil and other high fire risk materials MEANS OF ESCAPE (SOLAS (A/88 RH (12/28)) Stairways and ladders providing means of escape to lifeboat and life raft embarkation deck(s) from all passenger and crew spaces and other spaces where crew normally employed confirmed. Means of escape from special category spaces confirmed Means of escape from machinery spaces confirmed All escape routes clear of rubbish	X X X
DD.1 DD.2 DD.3 EE.1 EE.2 EE.3	Fire insulation in good condition and in accordance with approved plan (including openings in 'A' and 'B' class divisions, ventilation systems, windows and side scuttles and the use of combustible material). DRAFFSTOPS: SMOKFHOLES, BETGA (SOLAS) (A/88 RUL2/35) Draft stops behind linings, etc. verified Smoke holes verified All machinery rooms, bilge's, etc., clear of oil and other high fire risk materials MEANS OF ESCAPE (SOLAS / 4/88 RUL2/38) Stairways and ladders providing means of escape to lifeboat and life raft embarkation deck(s) from all passenger and crew spaces and other spaces where crew normally employed confirmed. Means of escape from special category spaces confirmed Means of escape from machinery spaces confirmed All escape routes clear of rubbish	X X

FFE CAREST	DRENCHER'S YSTEM (SOLAS 74/88) RIII 2/97/64. 24 24 24 24 24 24 24 24 24 24 24 24 24	K.8344
FF.1	Zones operated individually	⊡
FF.2	Fire mains connection verified	⊡
FF.3	Remote starting of pump from valve room verified	
FF.4	Zone plan at operating station	
FF.5	General labeling clear	
FF.6	Drainage satisfactory	
GG	TELECTRICAL DETECTION SYSTEM (SOLAS 7/4/88) RULE 2/1/5/13/3/5/2017	
GG.1	Heads operated and visual and audible alarm given on the Bridge	
GG.2	Audible alarm automatically sounded in crew accommodation and service spaces, control stations and category 'A' machinery spaces if bridge alarm not acknowledged within 2 minutes	
GG.3	System plan onboard	x
GG.4	Spare heads available	×
HH. A. X.	SMOKE DETECTION SYSTEM (SAMPLE EXTRACTION) SYSTEM (SOLAS 74/88 R H 2/13-1)	
нн.1	System operated and alarms verified	
	BREAK-GLASS FIRE ALARMS (SOLAS DA & SIR III 2/13 (500))	
U.I	Individual alarms operated and corresponding visual and audible signals given on the Bridge	
П.2	General labeling clear	x
		<u> </u>
JLFFA	ALARM SYSTEM AND PUBLICAD DRESS SYSTEM (SOLAS 114/88 RUL 2/40) A North College	\$ 14 A. L.
II.1	Alarm to summon crew operated and separation from passenger alarm verified	x
JJ.2	Public address system throughout accommodation and service spaces and control stations verified	x
JJ.3	Fire patrol keys and duration confirmed	x
· KaK Kalanga	CARRIAGE/OF DANGEROUS GOODS I(SOUAS 1/4/88) RHI (2/40) (14/4/4/4/20)	
		102 20 A to 200 M
KK.1	Arrangement per attachment to Form 2114 verified	

(1/)					
Surveyor's Signatur	Name of Ship	Date	LR/IMO Number	Report Number	Page
GKY /		28			
THE THE PERSON NAMED IN TH		<1.7.00		1	
N.J. HASTINGS / À. MADDEN	NIEUW AMSTERDAM		80024014	VCR 000154	22

PEC PER	NOTICES: (SOLAS 74/88)R (1-2/40)	# 12 h
LL.1	Passenger cabin muster and emergency instructions displayed	x
LL.2	Signs indicating escape routes displayed and adequately illuminated	x

MM.	SURVIVALICRAET)RESQUE BG (SOLAS 74/88 R III/19: 2048)	ATLAI	NDI ASSICICIONE	DILAUNCHIR	GANI Lega	REGOVERY	APPLIANCES		
	LIFEBOATS								
MM.1	Lifeboats turned out and lowered to Embarkati	on Deck,	at time of survey, OF	(give numbers)					
	Lifeboats turned out, lowered and maneuvered	1 sha	des faire sombored	1 through 16					
MM.2	Lifeboats turned out, lowered and maneuvered	III DIE WA	tter (Rive immoets)	-1 timougn 10					
MM.3	Each motor lifeboat engine readily started and operated satisfactorily, ahead and astern								
MM.4	Each motor lifeboat provided with sufficient fu	et for 24	hours continuous ope	ration			x		
MM.5	Air cases removed, found or placed in good co	ndition r	enlaced and secured	OR					
14111.5									
MM.6	Built-in buoyancy found in good condition as f	ar as coul	d be seen				x		
MM.7	Each lifeboat found in good condition						x		
MM.8	All sheaves, blocks falls, lifting hooks, hook foundations and securing arrangements, release arrangements and all moving parts								
	found free and well lubricated or made good a			•	•				
MM.9	On-load release gear and hydrostatic lock (if provided)								
MM.10	Dates when lifeboat falls renewed or reversed								
MM.10	(See Note 2 on page 1)								
			Renewed	Reversed		Renewed	Reversed		
i		1	02/95	02/00	2	02/95	02/00		
ļ		3	09/94	09/99	4	02/95	02/00		
ļ		5	02/95	02/00	6	01/94	01/99		
		7	07/92	07/97	8	01/95	01/00		
)		9	05/92	05/97	10	01/95	01/00		
}		11	05/92	05/97	12	02/97			
}	·	13	08/98		14	09/96	03/99		
		15	05/97		16	08/98			
		17		· · · · · · · · · · · · · · · · · 	18				
	,	19	-		20				
		21			22				
		23			24				
	· ·	25			26				
		27			28				
		29		<u> </u>	30				

\sim	·				·
Surveyor's Signature	Name of Ship	Date	LR/IMO Number	Report Number	Page
		70 cm			
		140.7.00			
N.J. HASTINGS 7A. MADDEN	NIEUW AMSTERDAM		80024014	VCR 000154	23

11.1 Number of persons the boat is certified to carry 11.2 Rowing oars/steering oar if applicable 11.3 Thole pin and crutch permanently attached or equivalent arrangement, one for each oar 11.4 Plugs with chain attached, one for each drain valve 11.5 Number of automatic drain valves fitted 11.6 Rudder attached with tiller 11.7 Lifetine bucketed around outside of boat 11.8 Bitge pumps manually operated (1) 11.9 Lockers for small items of equipment 11.10 Painter (1) secured to stern, (1) secured forward with release device able to operate under tension 11.11 Boat hooks (2) 11.12 Food ration of approved type in airtight receptacles stowed in watertight containers totaling not less than 10,000kJ per person 11.13 Fresh water, 3 litres or 6 pints per person in watertight receptacles or a desalting apparatus 11.14 Parachute signals, red (4) 11.15 Hand flares, red (6) 11.16 Buoyant smoke signals, orange (2) 11.17 Baler, buoyant (1) 11.18 buckets with lanyard (2)
Thole pin and crutch permanently attached or equivalent arrangement, one for each oar In 4 Plugs with chain attached, one for each drain valve In 5 Number of automatic drain valves fitted In 6 Rudder attached with tiller In 7 Lifeline bucketed around outside of boat In 8 Bitge pumps manually operated (1) In 9 Lockers for small items of equipment In 10 Painter (1) secured to stern, (1) secured forward with release device able to operate under tension In 11 Boat hooks (2) In 11 Food ration of approved type in airtight receptacles stowed in watertight containers totaling not less than 10,000kJ per person In 11 Parachute signals, red (4) In 11 Parachute signals, red (6) In 11 Boat, buoyant (1) In 12 Baler, buoyant (1)
11.4 Plugs with chain attached, one for each drain valve 11.5 Number of automatic drain valves fitted 11.6 Rudder attached with tilter 11.7 Lifeline bucketed around outside of boat 11.8 Bilge pumps manually operated (1) 11.9 Lockers for small items of equipment 11.10 Painter (1) secured to stern, (1) secured forward with release device able to operate under tension 11.11 Boat hooks (2) 11.12 Food ration of approved type in airtight receptacles stowed in watertight containers totaling not less than 10,000kJ per person 11.13 Fresh water, 3 litres or 6 pints per person in watertight receptacles or a desalting apparatus 11.14 Parachute signals, red (4) 11.15 Hand flares. red (6) 11.16 Buoyant smoke signals, orange (2) 11.17 Baler, buoyant (1)
Number of automatic drain valves fitted 11.6 Rudder attached with tiller 11.7 Lifeline bucketed around outside of boat 11.8 Bilge pumps manually operated (1) 11.9 Lockers for small items of equipment 11.10 Painter (1) secured to stern, (1) secured forward with release device able to operate under tension 11.11 Boat hooks (2) 11.12 Food ration of approved type in airtight receptacles stowed in watertight containers totaling not less than 10,000kJ per person 11.13 Fresh water, 3 litres or 6 pints per person in watertight receptacles or a desalting apparatus 11.14 Parachute signals, red (4) 11.15 Hand flares, red (6) 11.16 Buoyant smoke signals, orange (2) 11.17 Baler, buoyant (1)
11.6 Rudder attached with tiller 11.7 Lifeline bucketed around outside of boat 11.8 Bilge pumps manually operated (1) 11.9 Lockers for small items of equipment 11.10 Painter (1) secured to stern, (1) secured forward with release device able to operate under tension 11.11 Boat hooks (2) 11.12 Food ration of approved type in airtight receptacles stowed in watertight containers totaling not less than 10,000kJ per person 11.13 Fresh water, 3 litres or 6 pints per person in watertight receptacles or a desalting apparatus 11.14 Parachute signals, red (4) 11.15 Hand flares. red (6) 11.16 Buoyant smoke signals, orange (2) 11.17 Baler, buoyant (1)
Lifeline bucketed around outside of boat It also a Bilge pumps manually operated (1) Lockers for small items of equipment Lockers for small items of equipment It also a Painter (1) secured to stern, (1) secured forward with release device able to operate under tension It also a Boat hooks (2) It also a Food ration of approved type in airtight receptacles stowed in watertight containers totaling not less than 10,000kJ per person It also a Fresh water, 3 litres or 6 pints per person in watertight receptacles or a desalting apparatus It also apparatus
Bilge pumps manually operated (1) Lockers for small items of equipment X Lockers for small items of equipment X 11.10 Painter (1) secured to stern, (1) secured forward with release device able to operate under tension X 11.11 Boat hooks (2) X 11.12 Food ration of approved type in airtight receptacles stowed in watertight containers totaling not less than 10,000kJ per person X 11.13 Fresh water, 3 litres or 6 pints per person in watertight receptacles or a desalting apparatus X 11.14 Parachute signals, red (4) X 11.15 Hand flares, red (6) X 11.16 Buoyant smoke signals, orange (2) X II.17 Baler, buoyant (1)
Lockers for small items of equipment 11.10 Painter (1) secured to stern, (1) secured forward with release device able to operate under tension X 11.11 Boat hooks (2) X 11.12 Food ration of approved type in airtight receptacles stowed in watertight containers totaling not less than 10,000kJ per person X 11.13 Fresh water, 3 litres or 6 pints per person in watertight receptacles or a desalting apparatus X 11.14 Parachute signals, red (4) X 11.15 Hand flares. red (6) X 11.16 Buoyant smoke signals, orange (2) X Baler, buoyant (1)
Painter (1) secured to stern, (1) secured forward with release device able to operate under tension X 11.11 Boat hooks (2) X 11.12 Food ration of approved type in airtight receptacles stowed in watertight containers totaling not less than 10,000kJ per person X 11.13 Fresh water, 3 litres or 6 pints per person in watertight receptacles or a desalting apparatus X 11.14 Parachute signals, red (4) X 11.15 Hand flares, red (6) X 11.16 Buoyant smoke signals, orange (2) X 11.17 Baler, buoyant (1)
Boat hooks (2) Food ration of approved type in airtight receptacles stowed in watertight containers totaling not less than 10,000kJ per person Fresh water, 3 litres or 6 pints per person in watertight receptacles or a desalting apparatus X Parachute signals, red (4) Hand flares. red (6) Buoyant smoke signals, orange (2) X Baler, buoyant (1)
Food ration of approved type in airtight receptacles stowed in watertight containers totaling not less than 10,000kJ per person Fresh water, 3 litres or 6 pints per person in watertight receptacles or a desalting apparatus R Parachute signals, red (4) Hand flares, red (6) Buoyant smoke signals, orange (2) R Baler, buoyant (1)
Fresh water, 3 litres or 6 pints per person in watertight receptacles or a desalting apparatus 11.14 Parachute signals, red (4) 11.15 Hand flares, red (6) 11.16 Buoyant smoke signals, orange (2) 11.17 Baler, buoyant (1)
11.14 Parachute signals, red (4) 11.15 Hand flares, red (6) 11.16 Buoyant smoke signals, orange (2) 11.17 Baler, buoyant (1)
Hand flares. red (6) 11.16 Buoyant smoke signals, orange (2) 11.17 Baler, buoyant (1)
11.16 Buoyant smoke signals, orange (2) 11.17 Baler, buoyant (1)
Baler, buoyant (1)
11 18 buckets with lanvard (2)
Hatchets with lanyard (2), one at each end of boat
11.20 Compass in binnacle, efficiently aluminised or illuminated
Sea anchor (1) with shock resistant hawser and a tripping line
Dipper, rust proof with lanyard (1)
11.23 Graduated drinking vessel, rust proof (1)
11.24 First aid outfit, approved type in watertight case (1)
Electric torch, waterproof, suitable for morse code signaling (1), with spare set of batteries and spare bulb in waterproof container
11.26 Daylight signaling mirror (1)
I 1.27 Jack-knife attached to boat with lanyard (1)

/ //					
Surveyor's Signature	Name of Ship	Date	LR/IMO Number	Report Number	Page
1 (X-1		28-5- MX			
N I HASTING TA MADDEN	NIEUW AMSTERDAM	-0 3 00	80024014	VCR 000154	24

11.28	Whistle or equivalent sound signal (1)	x
11.29	Fishing tackle (1) set	x
11.30	Lifesaving signals on a waterproof card or in a waterproof container	x
11.31	Short ladder or other means of climbing into upright boat from the water	x
11.32	Skates or fenders (and skids if required) to facilitate launching against adverse list	x
11.33	Hand holds on underside of hull (only required on non self-righting lifeboats)	х
11.34	A survival manual	x
11.35	Six doses of anti-seasickness medicine per person	x
11.36	One seasickness bag per person	x
11.37	Tin openers (3)	x
11.38	Buoyant rescue quoit (2) attached to not less than 30m of buoyant line	X
11.39	Searchlight (1)	x
11.40	Efficient radar reflector (1)	x
11.41	Thermal protective aids (for 10% or 2 persons, whichever is greater)	x
11.42	Manually controlled internal and external lamps able to be operated for at least 12 hours	x
11.43	Sufficient tools for minor adjustments to the engine and its accessories	x
MM.12	Additional requirements for partially enclosed lifeboats if vessel trades on restricted service (SOLAS 74/88 R III/42)	
12.1	An effective means of bailing, OR	
12.2	The lifeboat is fitted with automatic self-bailing arrangements	
12.3	A permanently attached foldable right anti-exposure cover in way of open part of boat	⊡
12.4	Foldable cover is provided with means of collecting water	
MM.13	Motor lifeboats (SOLAS 74/88 R III/41)	
13.1	Starting system with two independent rechargeable energy sources	x
13.2	Fuel capacity sufficient for 24 hours running	x
13.3	Fire extinguisher, portable, suitable for oil fires	×
13.4	Propeller guard is provided	x
13.5	Exhaust pipe is provided with means to prevent ingress of water to engine	x
13.6	Engine transmission and accessories are enclosed in the fire retardant easing	х
L	· 10	

K./_/_					
Surveyor's Signature	Name of Ship	Date	LR/IMO Number	Report Number	Page
\cup	•	71 -			
1 54- 1		120.5.00			
N.J. HASTINGS / A. MADDEN	NIEUW AMSTERDAM		80024014	VCR 000154	25

13.7	Means are provided for recharging engine starting, radio and searchlight batteries		x
13.8	Water resistant instructions for starting and operating the engine are provided		x
MM.14	Additional requirements for pre-SOLAS 1983 lifeboats (SOLAS 74 R III/11)		
14.1	Bilge keels or rails		×
14.2	Grab lines gunwale to gunwale (2 minimum)		x
14.3	Light buoyant heaving tines (2)		x
14.4	Mast with galvanised wire stays and orange sail (not required for M or MP boats)		⊡
14.5	Cover, highly visible, for protecting occupants		x
14.6	Lamp with sufficient oil for 12 hours (1)		x
14.7	Matches in watertight containers (2)		x
14.8	Storm oil 4.5 its (1 gallon)		x
14.9	Storm oil container, for attaching to sea anchor		x
14.10	Bowsing tackles to hold boat against ship's side		x
MM.15	All boats (SOLAS 74/88 R III/41)	•	х
ММ.16	Dimensions and number of persons it is permitted to carry permanently marked thereon		x
ММ.17	Name and Port of Registry of the ship to which the lifeboat belongs painted on each side of bow		x
MM.18	It is possible to identify the ship to which the lifeboat belongs and the number of the lifeboat when viewed from above	:	· 🗶
мм.19	Will lifeboat pyrotechnics expire before date of next survey Indicate boat numbers:	Yes	No x
MM.20	Any lifeboat pyrotechnics renewed at this time Indicate boat numbers and dates:	Yes 🔲	No x
MM.21	All survival craft launching and recovery appliances found satisfactory when examined as far as practicable		
MM.22	Each lifeboat fitted with retro reflective materials		
MM.23	Rescue boats (SOLAS 74/88 R III/47)		n
MM.24	Rescue boats examined, found in good condition and fully equipped	•,	
MM.25	Date of last service of rescue boat, (if applicable)		N/A
мм.26	Launching and recovery appliances found satisfactory when examined as far as practicable	•	
мм.27	Release hooks falls and associated moving parts (blocks, sheaves, etc.) were found free and well lubricated or made a at time of survey	good	⊡
MM.28	The rescue boat was fitted with retro reflective material		•
	A ()		

\mathcal{L}	,				
Surveyor's Signature	Name of Ship	Date	LR/IMO Number	Report Number	Page
I DI		750	•		İ
27		50.2.00			Í
N.J. HASTINGS A. MADDEN	NIEUW AMSTERDAM		80024014	VCR 000154	26

MM.29	Rescue boat equipment - General Requirements (SOLAS 74/88 R III/47)	
29.1	Sufficient oars or paddles to make headway in calm sea	⊡
29.2	Thole pins, crutches or equivalent for each oar	⊡
29.3	Thole pins or crutches attached by lanyard or chain	⊡
29.4	Buoyant baler (1)	<u> </u>
29.5	Binnacle containing an efficient luminous compass (1)	⊡
29.6	Sea anchor with tripping line at least 10m in length (1)	⊡
29.7	Painter of sufficient length and strength at fore end (1)	·
29.8	Buoyant line not less than 50m in length of sufficient strength to tow a liferaft (1)	•
29.9	Waterproof electric torch for message signaling (1)	
29.10	Spare set of batteries and bulb in watertight container	•
29.11	One whistle or equivalent sound signal (1)	⊡
29.12	First aid kit in watertight case (1)	•
29.13	Buoyani quoits attached to line at least 30m in length (2)	
29.14	A searchlight able to efficiently illuminate a light coloured object at night which has a width of 18m at a distance of 180m	
29.15	A searchlight able to operate continuously for at least 3 hours	
29.16	An efficient radar reflector	
29.17	Thermal protective aids for at least 20% of complement or 2 persons, whichever is the greater	⊡
MM.30	Additional requirements for rigid rescue boats (SOLAS 74/88 R III/47)	
30.1	A boat hook	⊡
30.2	A bucket	⊡
30.3	A knife or hatchet	
MM.31	Additional requirements for inflatable rescue boats (SOLAS 74/88 R III/47)	
31.1	A buoyant safety knife	•
31.2	Two sponges	⊡
31.3	An efficient manually operated bellows or pump	<u> </u>
31.4	A puncture repair kit in a suitable container	<u> </u>
31.5	A safety boat hook	-
MM.32	All survival craft equipped as above	<u> </u>
L		

$\cdot L / I - V = -$					
Surveyor's Signature	Name of Ship	Date	LR/IMO Number	Report Number	Page
		20-			1
1 204	· ·	ス・フ・氷ー		Ĭ	
		120 2 00	00004044	1100 000164	1 22
N I HASTINGS / A. MADDEN	NIEUW AMSTERDAM	1	80024014	VCR 000154	21

NN.11	tested and found satisfactory Lifeboat launching instructions posted	x
NN.10	Two-way communications system tested and found to be satisfactory, life-saving appliance communications equipment including two-way VHF radio telephone apparatus, and radar transponders together with their stowage arrangements	x
NN.9	Symbols as required posted throughout the vessel	x
NN.8	All embarkation arrangements and launching gear found to be satisfactory when examined as far as practicable	x
NN.7	Operative test of all emergency power supplies, emergency lighting and general alarm systems satisfactorily carried out	x
NN.6	Abandon ship audible signals operating satisfactorily	x
NN.5	Lifeboat embarkation ladders found or placed in good condition	x
NN.4	Lifelines on davit spans* and howsing tackles* were found or placed in good condition (if applicable)	x
NN.3	Illumination of stowage and launching positions found in working order	x
NN.2	Means of preventing discharge of water into boat found satisfactory	
NN.I	Emergency power lighting and general alarm all operating satisfactorily	x
NN:	SURVIVAL CLASSED LAUNCHING AND EMBARKATION ARRANGEMENTS (SOLAS 74/88 R TIV6,9,11,12,13,15,16,22,24)	

Surveyor's Signature	Name of Ship	Date	LR/IMO Number	Report Number	Page
		28.5.30	=		
N.J. HASTINGS / A. MADDEN	NIEUW AMSTERDAM		80024014	VCR 000154	28

00 🚎 🖈	INFL)	ATABLE LIFE RAF ONTHS): "(SOLAS 7	TAND HYDROSTATT 4/88 R III/9, 19)	GRELEASE/SERV	iging (servicin	G DUE EVERY	
00.1	1	1	**************************************			**	Launching
	No.	Makers Name	Serial Number	No. Persons	Date Serviced	Servicing Agent	Appliance
	1	BEAUFORT	239	25	05/00	DBC	YES
	2	VIKING	C090190	25	05/00	VIKING 627	YES
	3	BEAUFORT	65350	25	05/00	DBC	YES
	4	BEAUFORT	65336	25	05/00	DBC	YES
	5	BEAUFORT	65342	25	05/00	DBC	YES
	6	BEAUFORT	195	25	05/00	DBC	YES
	1 7	BEAUFORT	64441	25	05/00	DBC	YES
	8	BEAUFORT	62708	25	05/00	DBC	YES
	9	BÉAUFORT	65331	25	05/00	DBC	YES
	10	BEAUFORT	65325	25	05/00	DBC	
	111	BEAUFORT	4/63997	25	05/00	DBC	YES
	12	BEAUFORT	64428	25	05/00	DBC	YES
	13	VIKING	H120699	25	07/99		YES
	14	BEAUFORT	65326	25	05/00	VIKING 627	YES
	15	BEAUFORT	65304	25		DBC DBC	YES
	16	BEAUFORT	65351	25	05/00 05/00	DBC	YES
	17	BEAUFORT	65333	25			YES
	18	VIKING	B100190		05/00	DBC	YES
	19	VIKING		25	05/00	VIKING 627	YES
	20		G070190	25	05/00	VIKING 627	YES
		BEAUFORT	65347	25	05/00	DBC	YES
	21	BEAUFORT	65355	25	05/00	DBC	YES
	22	BEAUFORT	65328	25	05/00	DBC	YES
	23	BEAUFORT	65306	25	05/00	DBC	YES
	24	BEAUFORT	65352	25	05/00	DBC	YES
	25	VIKING	G060190	25	05/00	VIKING 627	YES
	26	VIKING	G030190	25	05/00	VIKING 627	YES
	27	VIKING	G040190	25	05/00	VIKING 627	YES
	28	BEAUFORT	65354	25	05/00	DBC	YES
	29	BEAUFORT	65340	25	05/00	DBC	YES
	30	VIKING	C030190	25	05/00	VIKING 627	YES
	31	BEAUFORT	65349	25	05/00	DBC	YES
	32	VIKING	H040190	25	05/00	VIKING 627	YES
	33	BEAUFORT	65343	25	05/00	DBC	YES
	34	BEAUFORT	64419	25	12/00	DBC	YES
	35	BEAUFORT	65335	25	05/00	DBC	YES
	36	VIKING	C020190	25	05/00	VIKING 627	YES
	37	BEAUFORT	230	25	12/99	DBC	YES
	38	BEAUFORT	250	25	10/99	DBC	YES
	39						
	40						
	41						
	42						
	43						
	44						
	45						
	46						
	47						
	48						
(•					

Surveyor's Significate	Name of Ship	Date	LR/IMO Number	Report Number	Page
1 424		28,5,00			
N.J. HASTINGS / A. MADDEN	NIEUW AMSTERDAM	70 3	80024014	VCR 000154	29

	49	
	50	
	51	<u> </u>
00.2	The inflatable life rafts and any associated hydrostatic release mechanism have been serviced* during the previous twelve months renewed and a valid service Certificate sighted SERVICING PERIOD EXTENDED TO 17 MONTHS BY	X
00.3	NATIONAL AUTHORITY Life raft stowage will facilitate proper release including float free facility where required	x
00.4	Launching instructions posted	X

P.1	The embarkation arrangement of inflatable life rafts and, where are life rafts found satisfactory	provided, the launching arrangements	of davit	[X
P.2	Date life raft davit falls renewed or reversed	,		[X
	(See note 2 on page 1)	Davit	Renewed	Reversed
		. 1	08/96	
		2	06/96	· · · · · · · · · · · · · · · · · · ·
		3	10/98	
		4	10/98	
	· ·	5	05/00	
		. 6	10/95	
		7		
		. 8		
		9		
	·	10		
		11		•
		12		

QQ.=*.	TURENCKETS (SOPAS 74/88) RUIU 7/8/2011 4 2 3 3 3 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	falk (Aa)
QQ.1	Complete number of approved lifejackets, as shown on Form 2114 each with whistle and light per record.	X
	(Number: 2040, plus 137 for children)	_
QQ.2	Each lifejacket found in good condition	
QQ.3	Lifejackets stowed in accessible and clearly marked places	x
QQ.4	Last date of service for inflatable lifejackets (if applicable)	
QQ.5	Each lifejacket fitted with retro reflective material	X

1/1					
Surveyor's Signature	Name of Ship	Date	LR/IMO Number	Report Number	Page
J W	1	0000		1	!
1 9-1-	1	1 25.6.30		1	
N.J. HASTINGS A MADDEN	NIEUW AMSTERDAM		80024014	VCR 000154	30

		•
ARR-FOR CH	RUHEBUOYS; IMMERSIONISUITIS AND THERMALEPROTECTION: AUDS (SOLAS TAL88 R. TUTA CI	31,33,34)
RR.1	All lifebuoys were:	x
RR.1.1	Complete in number as shown on Form 2114 and in good condition. (Number: 24)	x
RR.1.2	Of highly visible colour, fitted with beckets and readily accessible	x
RR.1.3	Marked in block letters with name and port of registry of ship	x
RR.1.4	Fitted with lines, lights or light and smoke as on Form 2114	x
RR.1.5	Capable of being rapidly cast loose	
RR.1.6	Fitted with retro reflective material	x
RR.2	Immersion suits and thermal protective aids complete as on Form 2114 and in good condition, including T.P.A.'s stowed in survival craft as equipment	
SSEC OF THE	CERTIFIED BIFEBOATMEN (SOLASVA)88RCIII/(O) CARASTA SECTION (SOLASVA)88RCIIII (SOLASVA)88RCIIII/(O) CARASTA SECTION (SOLASVA)88RCIIII/(O) CARASTA SECTION (SOLAS	Alles de la cerci
SS.1	Sufficient onboard to satisfy flat requirements - 70	X
SS.2	Engineer assigned to each motorised survival craft	×
\$S.3	Instructions for manning survival craft and supervision	x
m sanda	TEMERGENCY LIGHTS: (SOEASW488 RAII) (42 TRAII) (11)	
TT.1	All emergency lights tested	x
TT.2	Supplementary emergency lights tested (Ro-Ro Passenger ships only	x
TT.3	Spare bulbs for emergency lights on board	x

<u> </u>					
Surveyor's Signature	Name of Ship	Date	LR/IMO Number	Report Number	Page
		28.C.M			1
N.J. HASTINGS A. MADDEN	NIEUW AMSTERDAM	C 0, 2 00	80024014	VCR 000154	31

DILY.	SAFETY OF NAVIGATION (SOLAS 74/88) RAVID) WITH THE SAFETY OF NAVIGATION (SOLAS 74/88) RAVID) WITH THE SAFETY OF NAVIGATION (SOLAS 74/88) RAVID) WITH THE SAFETY OF NAVIGATION (SOLAS 74/88) RAVID) WITH THE SAFETY OF NAVIGATION (SOLAS 74/88) RAVID) WITH THE SAFETY OF NAVIGATION (SOLAS 74/88) RAVID) WITH THE SAFETY OF NAVIGATION (SOLAS 74/88) RAVID) WITH THE SAFETY OF NAVIGATION (SOLAS 74/88) RAVID) WITH THE SAFETY OF NAVIGATION (SOLAS 74/88) RAVID) WITH THE SAFETY OF NAVIGATION (SOLAS 74/88) RAVID) WITH THE SAFETY OF NAVIGATION (SOLAS 74/88) RAVID) WITH THE SAFETY OF NAVIGATION (SOLAS 74/88) RAVID) WITH THE SAFETY OF NAVIGATION (SOLAS 74/88) RAVID) WITH THE SAFETY OF NAVIGATION (SOLAS 74/88) RAVID (S	NUMBER OF STREET
	THE FOLLOWING FOUND IN SATISFACTORY CONDITION	
UU.1	Gyro compass:	x
UU.2	Echo sounder:	х
UU.3	Magnetic compass(es) standard*, and spare*;	x
UU.4	Indicators for speed and distance*, rudder angle*, propeller revolutions*, propeller pitch and mode*	x
บบ.ร	Means of taking bearings through 360° and means of communication between standard compass position and navigation control position; x	х
UU.6	. Auto-pilot;	x
UU.7	Auto-pilot changeover instructions;	x
UU.8	Steering gear changeover instructions;	x
UU.9 .	Automatic radar plotting aid;	x
UU.10	Heading information at emergency steering position;	x
UU.11	Radar(s)*;	<u> </u>
UU.12	Radio-direction finder	EXEMPTION
UU.13	RDF Date of last verification/calibration* of:	27/03/00
	Compass	2.705/40

W. A.	SIGNALING APPARATUS (SOLAS 74/88 R. VALIAND INTERNATIONAL COLUSION FRANCISCO SUSSION	
	THE FOLLOWING FOUND IN SATISFACTORY CONDITION .	
VV.1	Daylight signaling lamp and source of power;	X
VV.2	Forecastle belt:	X
VV.3	Gong;	X
VV.4	Ship's Whistle:	X
VV.5	Three black ball shapes;	X
VV.6	One black diamond shape:	X
VV.7	Cylindrical shape (if provided)	x

\bigwedge					
Surveyor's Signatur	Name of Ship	Date	LR/IMO Number	Report Number	Page
100		28.5.00			
N.J. HASTINGS A MADDEN	NIEUW AMSTERDAM	1-0 3 -0	80024014	VCR 000154	32

						
WW N	NAVIGATION LIGHTS (INTERNATIONAL COLLESION	uregulationsir	20 TO 24, 27	FO:30;33'		
ww.ı	Sidelight inboard screens painted matte black		•	x		
WW.2	Navigation lights in good condition and operating satisfactorily					
		Majanely				
WW.3	Navigation light failure warning device: Visual/Audible* on bridge operating ef	TICLE HUY		X		
XXX : 5 - 6	BRIDGE DISTRESS SIGNALS (SOLAS VAISS RVIII/6 X 17	S. S. S. S. S. S. S. S. S. S. S. S. S. S		er er er er er er er er er er er er er e		
	INDICATE EXPIRY DATE(E) OR MANUFACTURE DATE (M) OF THE FOLLO	,				
	•	E	M	Date		
XX.1	Line throwing rockets, and	E		03/2002		
XX.2	Igniter cartridges (if applicable)					
XX.3	12 red parachute signals	E		09/2001		
XX.4	Line throwing rockets and ship's distress flares, all found to be satisfactory			x		
		· Will St. Real St. Participation St.				
	MUSTERS AND DRIELS (SOLAS 174/88) III/18) 45 94					
YY.1	Fire drill carried out					
YY.2	Realistic crew Muster and Lifeboat drill carried out					
77.	= RILOT LADDER'S) AND ACCOMMODATION GADDER	7/S\#7/S\M\#A\\$#/#88	D(8)/6588 500			
ZZ.)	Side ropes, man ropes and steps in good condition	NO E COPERO E MARIO E	(A			
		_		×		
ZZ.2	The condition and illumination of the (adder(s) and boarding position in good order					
ZZ.3	A heaving line and one of the lifebuoys with self-igniting light was readily to hand					
ZZ.4	*Pilot ladder(s) and *accommodation ladder(s) found to be in good condition			x		
ZZ.5	*Pilot ladder(s) and *accommodation ladder(s) raised and examined in position			x		
AAA:	MECHANICAL/PILIOT HOIST: (SOHAST/4/88/R:V/17)			建 型建設的		
AAA.1	Hoist was rigged examined under working conditions and found satisfactory					
AAA.2	Hoist was found in a satisfactory condition and operational			<u>-</u>		
	<u> </u>					

Surveyor's Signature	Name of Ship	Date	LR/IMO Number	Report Number	Page
1 -11/	*	70.00		1	1
1 104		128,200			
N.J. HASTINGS A. MADDEN	NIEUW AMSTERDAM		80024014	VCR 000154	33